

Cordless & Light model

- Quick startup and restoration less than 1 sec
- Quickly display measured values with mode for holding Peak
- Supply with external power or dry battery
- Energy saving mode with acceleration sensor